

  				Relatório nº	7
				Data do relatório	26/05/2025
				Dia da semana	Segunda-Feira
Relatório de Obra				Contrato	80/2024
Obra	Construção de cobertura de quadra esportiva no Parque Nossa Senhora das Dores II			Prazo contratual	334 dias
Local	Parque Nossa Senhora das Dores			Prazo decorrido	334 dias
Contratante	Prefeitura Municipal de Limeira	Responsável	Dagoberto de Campos Guidi (Gestor Contratual), Adriano C. Camacho (Fiscalização), Renato H. Maluf (Execução)	Prazo a vencer	-24 dias

Ocorrências (1)
Construção de calçamento no entorno

Fotos (8)



A white dump truck is parked on a dirt road, unloading material into a blue container. The truck is positioned in front of a large, white, corrugated metal building. A person is standing near the truck. The background shows a clear blue sky and some trees.



A close-up view of a concrete slab with rebar. The slab is being poured or finished, and the rebar is visible. The concrete is a light gray color. The background shows a chain-link fence and some trees.



A view of the gravel area under the structure. The gravel is dark gray and is being spread or compacted. The concrete pillars of the structure are visible in the background.



A view of the concrete pillars and roof structure. The pillars are white and the roof is made of corrugated metal. The ground is a mix of dirt and gravel. A chain-link fence is visible in the background.



A view of the completed concrete path. The path is a light gray color and runs alongside the concrete pillars. The background shows a clear blue sky and some trees.



A view of a wheelbarrow and construction materials. The wheelbarrow is a small, three-wheeled cart with a black frame and a red wheel. It is parked on a concrete path. The background shows a chain-link fence and some trees.

